



MERIDIAN BRICK - ALDERSHOT CENTRE QUARRY
1775 KING RD., BURLINGTON,

Inspection Report

System Number:
Inspection Start Date: 12/06/2021
Inspection End Date: 12/10/2021
Inspected By: Nick Fowler
Badge #: 429

A rectangular box containing a handwritten signature in black ink, which appears to read "Nick Fowler".

(signature)

NON-COMPLIANCE/NON-CONFORMANCE ITEMS

This should not be construed as a confirmation of full compliance with all potential applicable legal requirement and BMPs. These inspection findings are limited to the components and/or activities that were assessed, and the legislative framework(s) that were applied. It remains the responsibility of the owner to ensure compliance with all applicable legislative and regulatory requirements.

If you have any questions related to this inspection, please contact the signed Provincial Officer.

INSPECTION DETAILS

This section includes all questions that were assessed during the inspection.

Ministry Program: Regulated Activity: SEWAGE : Industrial Sewage

Ministry Program: Regulated Activity: SEWAGE : Industrial Sewage

Question ID	WW_APPROVAL_100000	
Question	Question Type	Legislative Requirement
Is an Environmental Compliance Approval (ECA) required for this sewage works?	Information	OWRA 53 (1)
Observation		
Yes: This sewage works is subject to the ECA requirement.		

Question ID	WW_APPROVAL_110000	
Question	Question Type	Legislative Requirement
Do all sewage works currently being inspected have a valid Environmental Compliance Approval (ECA)?	Legislative	OWRA 53 (1)
Observation		
Yes: There is currently a valid ECA for the sewage works.		

Question ID	WW_APPROVAL_111000	
Question	Question Type	Legislative Requirement
Is the sewage works constructed in accordance with the Environmental Compliance Approval (ECA)?	Legislative	OWRA 53 (1)
Observation		
Yes: The sewage works is currently constructed in accordance with the ECA.		

Question ID	WW_SPILLS_100000	
Question	Question Type	Legislative Requirement
Does the facility have appropriate contingency plans and procedures for dealing with equipment breakdowns, potential spills and any other abnormal situations?	BMP	OWRA 53 (1)
Observation		
Yes: The facility does have contingency plans and procedures for dealing with abnormal situations.		

Question ID	WW_SPILLS_200000	
--------------------	------------------	--

Question	Question Type	Legislative Requirement
Has the facility had any spills during the inspection period?	Information	Not Applicable
Observation		
No: The facility has not had spills during the inspection period.		

Question ID	WW_AUDIT_SAMPLE_100000	
Question	Question Type	Legislative Requirement
Were Ministry audit samples collected during this inspection?	Information	Not Applicable
Observation		
Yes: Audit samples were collected during this inspection.		

Question ID	WW_IMPAIRMENT_100000	
Question	Question Type	Legislative Requirement
Were there no indications of a known or anticipated human health impact during the inspection and/or review of relevant material ?	Legislative	OWRA 30 (1)
Observation		
Yes: There were no indications of a known or anticipated human health impact associated with the operation of the sewage works.		

Question ID	WW_IMPAIRMENT_200000	
Question	Question Type	Legislative Requirement
Were there no indications of a known or anticipated environmental impact during the inspection and/or review of relevant material?	Legislative	OWRA 30 (1)
Observation		
Yes: There were no indications of a known or anticipated environmental impact associated with the operation of the sewage works		